

Connecting the Meanwell power supply

Contents kit.

9311016 1x Power supply 10A

9124493 this instruction

It is very important to locate the **plus and minus connection** of the power supply.

In case this 24V 10 A power supply is the replacement for the 24V 5A power supply then the plus and minus connections have **opposite locations**.

In the TDR ac the following wiring can be found:

Wire 71 = +

Wire 79 = -

